




LitePad™ Vector

Instructions for Converting to V-Mount Battery Operation

Materials Needed: 7/16" wrench, Philips head screw driver



1. Remove Power Supply (PSU) by unscrewing the 7/16" 1/4-20 nut that secures the PSU cradle to the unit. Unplug the barrel connector from the side of the Rear Control Panel.
2. Insert (4) supplied stand-offs into each exposed hole on the back of the unit, using the included Allen wrench.
3. Attach V-Mount battery holder using (4) supplied screws, using the Phillips head screwdriver.
4. Plug the supplied D-Tap cable into the battery holder and side of Rear Control Panel.

